


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. P-15

History of original corner establishment:

Not previously established



Description of corner evidence found:

None

Description of monument and accessories established to perpetuate the original location of this corner:

Corner location determined by survey and subdivision of Section 22.

At surveyed point set 2 1/2"x30" galvanized pipe with brass cap attached 12" in the ground stamped:

Built mound of stone to cap  
From which:

A 9" Pond. Pine bears N33°E 58.0 ft.  
scribed C 1/4 S22 BT

An 11" Pond. Pine bears S 83° E 129.4 ft.  
scribed C 1/4 S22 BT

Attached 54-3 and 54-4 signs to BT's. Painted blazes and 6' red ring around BT's. Attached brass washers LS1099 to foot blazes. Set metal post 5' north of corner with 54-4 and 54-9 signs.

Corner falls in clearing of the NE side 75' west of tree line.

Compass Declination: 18 1/2° East.

I hereby certify the above described corner monument and/or accessories was established as described on November 23, 1981.

Witnesses: Loren Huntsman  
Millard Wyatt  
Jeff Anderson

T2S	R36E
C 1/4	S22
1981	
OR PLS 1099	

**REGISTERED  
PROFESSIONAL  
LAND SURVEYOR**

*Gary L. Langlitz*  
**OREGON**  
JULY 22, 1977  
**GARY L. LANGLITZ**  
1099

Office of..... Surveyor..... County of..... Union.....  
Oregon  
State of..... I hereby certify that the within instrument was filed in this office  
for record on the 4 day of OCTOBER, 1982  
Howard L. Perry by *Gary L. Langlitz*  
(COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY  
SURVEYOR**

---

Date Received \_\_\_\_\_  
GPO 759-509

Date Filed \_\_\_\_\_

By \_\_\_\_\_

File No. 292-84B