


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:
 Corner not previously established.



No record of subsequent monumentation found in Union County survey records.

Description of corner evidence found:
 Corner not previously established.
 See map of survey dated June, 1989.


UNION COUNTY SURVEYOR	
Date Received	<u>8-22-89</u>
Date Filed	<u>8-22-89</u>
By	<u>G. LANGLITZ, DEPUTY</u>
File No.	<u>133-89 R</u>

Description of monument and accessories I established to perpetuate the original location of this corner: At position determined by survey, I set a 2½" x 30" aluminum pipe with aluminum cap marked as shown, 28 inches in the ground, from which:

- New BTs:
 A 12 inch diameter Douglas Fir bears S18°E, 25.23 feet marked CW 1/16 S24 BT
 A 12 inch diameter Douglas Fir bears N80°W, 27.23 feet marked X BT

- Painted a 6 inch red band around all BTs and attached bearing tree and land survey monument signs.
- Set a steel fencepost approximately 5 feet South with land survey monument and property boundary signs attached.
- Raised a small mound of stone around monument.

I hereby certify that the above corner point was perpetuated as hereon described on June 4, 1989.



**REGISTERED
 PROFESSIONAL
 LAND SURVEYOR**

Duane I. Griffith
 OREGON
 JULY 10, 1964
DUANE I. GRIFFITH
 644

I used a steel tape and magnetic compass in the establishment of new accessories. I used 17° East magnetic declination and the distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 644 to the BT blaze.

Office of..... County of.....
 State of....., I hereby certify that the within instrument was filed in this office
 for record on the..... day of....., 19.....
 by
 (COUNTY OFFICIAL) (DEPUTY)