


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:
Corner not previously established.



No record of subsequent monumentation found in Union County survey records.

Description of corner evidence found:
Corner not previously established.
See map of survey dated June, 1989.

UNION COUNTY SURVEYOR
Date Received <u>8-22-89</u>
Date Filed <u>8-22-89</u>
By <u>G. LANGLITZ, DEPUTY</u>
File No. <u>134-89 R</u>

Description of monument and accessories I established to perpetuate the original location of this corner: At position determined by survey, I set a 2½" x 30" aluminum pipe with aluminum cap marked as shown, 16 inches in the ground, from which:

New BTs:
A 16 inch diameter Douglas Fir bears S12°E, 85.37 feet marked C¼ S24 BT
A 16 inch diameter Ponderosa Pine bears S26°W, 51.04 feet marked C¼ S24 BT


Painted a 6 inch red band around all BTs and attached bearing tree and land survey monument signs.

Set a steel fencepost approximately 5 feet North with land survey monument sign attached.

Raised mound of stone around monument, 4 ft. base to top of cap.

I hereby certify that the above corner point was perpetuated as hereon described on June 12, 1989.

Witnesses: Rick Robinson and Jeff Petersen



**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

OREGON
JULY 10, 1964
DUANE I. GRIFFITH
644

I used a steel tape and magnetic compass in the establishment of new accessories. I used 17° East magnetic declination and the distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 644 to the BT blaze.

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19.....
..... by
(COUNTY OFFICIAL) (DEPUTY)