CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Not established on the original survey.

Index File No. 0-11

544664	
DIAGRA	1
T2S	R36E
SW $\frac{1}{16}$	21
•	

Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

Corner position established by survey and subdivision of Section 21. At surveyed point set $2\frac{1}{2}$ "x30" galvanized pipe with brass cap stamped:

Set pipe 14" in ground to rock with mound of stone to cap.

Bearing Trees:

A Tamarack 14" dia. bears S64°W 68.6 ft., scribed SW 1/16 S21 BT. A Tamarack 16" dia. bears S8°E 56.3 ft., scribed SW 1/16 S21 BT.

Set a metal fence post 6 ft. north with 54-4 and 54-9 signs. Painted trees and attached signs per Standard Specifications for Cadastral Surveys, USFS, Region 6, Oct., 1979.

Corner falls on toe of old Oregon Trail Highway in heavy underbrush.

Compass Declination: 18½°E.

I hereby certify the above described corner monument and/or accessories was established on August 3, 1982.

Witnesses: R. Orton

G. Wagoner

R. Scott

REGISTERED PROFESSIONAL AND SURVEYOR LANGLITZ

File No. 294-84 R

T2S R36E

1099

PLS

1982

Office of Surveyor County of Union State of Qregon I hereby certify that the within instrument was filed in this for record on the 4 day of OCTOBER 1082	s office
State of	UMION COUNTY SURVEYOR
Form R6-7100-57 (9/71)	Date Received 798-276
	Date Filed