## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Not established during original survey

Index	File No.	Q-13
DIAGRAM		
T2S	R36E	
S 1/16 S21 - S22		

Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner:

At surveyed point set 2 1/2"x30" galvanized pipe with brass cap stamped:

Set pipe 17" in ground to rock with mound of stone

and dirt to cap.
Bearing trees:

A P. Pine 23" dia. bears S7°E, 230.9 ft. scribed S 1/16 S22 BT.

A P. Pine 14" dia. bears N42°W, 170.0 ft. scribed S 1/16 S21 BT.

Attached 54-3 and 54-4 signs to both BT's and brass washer stamped LS 1099 to foot blazes. Painted blazes and 6" band around both B.T.'s red.

Attached 54-4 and 54-9 signs to metal post 6 ft. North of Cor.

Cor. falls in large opening approx. 530' south and 600' west of I-84 freeway.

Compass Declination: 18 1/2° East.

I hereby certify the above described corner monument and/or accessories was established on July 20, 1982.

Witnesses: Rodger Orton

Glen Wagoner

LAND SURVEYOR	
Harn I. Sanglit	
OR EGONO JULY 22, 1977	-
GARY L. LANGLITZ 1099	i

REGISTERED

**PROFESSIONAL** 

Office of Surveyor County of Unit	1099
State of Oregon I hereby certify that the within instrument for record on the Act day of Orober 1982  Howard L. Perry by John Orogon Deed	
Form R6-7100-57 (9/71)	Date Received
	Date Filed