


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:  
Corner not previously established.



No record of subsequent monumentation found in Union County survey records.

Description of corner evidence found:  
Corner not previously established.  
See map of survey dated June, 1989.

**UNION COUNTY SURVEYOR**

---

Date Received 8-22-89

Date Filed 8-22-89

By G. LANGLITZ, DEPUTY


File No. 136-89R

Description of monument and accessories | established to perpetuate the original location of this corner: At position determined by survey, I set a 2½" x 30" aluminum pipe with aluminum cap marked as shown, 20 inches in the ground, from which:

New BTs:  
A 14 inch diameter Ponderosa Pine bears S74°E, 45.95 feet marked S1/16 S24 BT  
A 20 inch diameter Ponderosa Pine bears S17°W, 16.00 feet marked S1/16 S23 BT

Painted a 6 inch red band around all BTs and attached bearing tree and land survey monument signs.  
Set a steel fencepost approximately 5 feet East with land survey monument and property boundary signs attached.  
Raised mound of stone around monument, 3 ft. base to top of cap.

I hereby certify that the above corner point was perpetuated as hereon described on June 2, 1989.



**REGISTERED PROFESSIONAL LAND SURVEYOR**

*[Signature]*  
OREGON  
JULY 10, 1964  
**DUANE I. GRIFFITH**  
644

I used a steel tape and magnetic compass in the establishment of new accessories. I used 17° East magnetic declination and the distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 644 to the BT blaze.

Office of..... County of.....  
State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....  
..... by .....

(COUNTY OFFICIAL) (DEPUTY)