


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:  
Corner not previously established.



No record of subsequent monumentation found in Union County survey records.

Description of corner evidence found:  
Corner not previously established.  
See map of survey dated June, 1989.


**UNION COUNTY SURVEYOR**  
Date Received 8-22-89  
Date Filed 8-22-89  
By G. LANGLITZ DEPUTY  
File No. 137-89 R

Description of monument and accessories | established to perpetuate the original location of this corner: At position determined by survey, I set a 2½" x 30" aluminum pipe with aluminum cap marked as shown, 22 inches in the ground, from which:

- New BTs:  
A 12 inch diameter Ponderosa Pine bears S77°E, 116.47 feet marked X BT  
(Existing North-South fence attached to tree)  
A 23 inch diameter double bole Ponderosa Pine bears N36°W, 292.95 feet marked SW1/16 S24 BT

- Painted a 6 inch red band around all BTs and attached bearing tree and land survey monument signs.  
Set a steel fencepost approximately 5 feet North with land survey monument and property boundary signs attached.  
Raised mound of stone around monument, 3 ft. base to top of cap.

I hereby certify that the above corner point was perpetuated as hereon described on June 4, 1989.



**REGISTERED PROFESSIONAL LAND SURVEYOR**

*[Signature]*  
OREGON  
JULY 10, 1964  
**DUANE I. GRIFFITH**  
644

I used a steel tape and magnetic compass in the establishment of new accessories. I used 17° East magnetic declination and the distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 644 to the BT blaze.

Office of..... County of.....  
State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....  
..... by .....

(COUNTY OFFICIAL)

(DEPUTY)