


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. R-3

History of original corner establishment:

In 1874, J. Hurlburt under G.L.O. contract No. 201:  
Set a Pine stake, 4 ft. long, 3 ins. thick, 2 feet  
in the ground for 1/4 Sec. Cor.  
Fir 8 in. dia. S13°E 25 lks.  
Pine 5 in. dia. N40°W 21 lks.



Description of corner evidence found:

None

Description of monument and accessories established to perpetuate the original location of this corner:

Corner location determined by single proportionate measurement between the SE and SW corners of Section 19.

At surveyed point:

Set a 2 1/2" x 30" galvanized pipe with brass cap attached stamped:

Pipe is set 24" in the ground, from which:  
A 12" Douglas Fir bears N37°E 36.0 ft. scribed 1/4 S 19 BT.

An 8" White Fir bears S2°W 20.0 ft. scribed 1/4 S 30 BT.

Attached 54-3 and 54-4 signs to BT's. Painted blazes and 6" red ring around trees. Attached brass washers LS1099 to foot blazes. Set metal post 5' North of corner with 54-4.

Corner falls on NE slope - 105' east from road No. 700.

Compass Declination: 18 1/2° East

I hereby certify the above described corner monument and/or accessories was established on November 4, 1981.

Witnesses: Loren Huntsman  
Millard Wyatt  
Greg Orton

T2S R36E  
1/4 S19  
-----|-----  
S30  
1981  
OR PLS 1099



Office of..... Surveyor..... County of..... Union.....  
State of..... Oregon..... I hereby certify that the within instrument was filed in this office  
for record on the... 4... day of... OCTOBER....., 1982  
..... Howard L. Perry..... by Gary L. Langlitz  
(COUNTY OFFICIAL) (DEPUTY)

DIXON COUNTY SURVEYOR  
Date Received \_\_\_\_\_  
Date Filed \_\_\_\_\_  
By \_\_\_\_\_  
File No. 297-84 R