


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. R-10

History of original corner establishment:

Not established during original survey



Description of corner evidence found:

None

Description of monument and accessories | established to perpetuate the original location of this corner:

Corner location determined by single proportionate measurement along south line of Section 21.

At surveyed point: set 2 1/2" x 30" galvanized pipe with brass cap 8" in the ground stamped:

Built mound of stone and dirt to cap.

From which:

A 12" P. Pine bears N75° W 49.2' scribed W 1/16 S21 BT.

A 16" P. Pine bears S27° W 73.3' scribed W 1/16 S28 BT.

Attached 54-3 and 54-4 signs to BT's. Painted blazes and 6" red ring around BT's. Attached brass washers LS 1099 to foot blazes. Set metal post 5' north of corner with 54-4 and 54-9 signs.

Corner falls on level ground on the north edge of small clearing.

Compass Declination: 18 1/2° East

I hereby certify the above described corner monument and/or accessories was established as described on November 19, 1981.

Witnesses: Loren Huntsman  
Millard Wyatt

T2S R36E  
S21  
W1/16 —+—  
S28  
1981  
OR PLS 1099

**REGISTERED  
PROFESSIONAL  
LAND SURVEYOR**

*Gary L. Langlitz*

**OREGON**  
JULY 22, 1977  
**GARY L. LANGLITZ**  
1099

Office of..... Surveyor..... County of..... Union.....  
Oregon

State of....., I hereby certify that the within instrument was filed in this office

for record on the... 4... day of... OCTOBER....., 1982

..... Howard L. Perry..... by *Gary L. Langlitz*.....  
(COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY  
SURVEYOR**

Date Received.....  
Date Filed.....  
By.....  
File No. 301-84R