


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. R-11

History of original corner establishment:

In 1874, J. Hurlburt under GLO contract No. 201, set
Pine post 4 ft. long, 3 ins. thick,
2 ft. in ground for 1/4 Sec. Cor.
Tamarack 10 in. dia. N5°W 28 lks.
Pine 10 in. dia. S20°E 67 lks.



Description of corner evidence found:

None

Description of monument and accessories established to perpetuate the original location of this corner:

Corner location determined by single proportionate measurement along the south line of Section 21:

At surveyed point set 2 1/2"x30" galvanized pipe with brass cap attached 24" in the ground stamped:

T2S R36E
S21
1/4 ———
S28
1981
OR PLS 1099

From which:

A 14" Doug. Fir bears N36°E 26.8 ft. scribed 1/4 S21 BT.


An 18" White Fir bears S32°W 37.7 ft. scribed: 1/4 S28 BT.

Attached 54-3 and 54-4 signs to BT's. Painted blazes and 6" red ring around BT's. Attached brass washer "LS 1099" to foot blazes. Set metal post 5' north of corner with 54-4 sign. Corner falls at the bottom of small SW-NE draw 135' south of dirt road.

Compass Declination: 18 1/2° East

I hereby certify the above described corner monument and/or accessories was established as described on November 19, 1981.

Witnesses: Loren Huntsman
Millard Wyatt



Office of.....Surveyor..... County of..... Union.....
State of..... Oregon..... I hereby certify that the within instrument was filed in this office
for record on the 4 day of OCTOBER..... 1982
Howard L. Perry by Gary L. Langlitz
(COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR

Date Received 7-28-82

Date Filed _____

By _____

File No. 302-84R