CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

In 1874, J. Hurlburt under GLO Contract No. 201

Set Pine post, 4 ft. long, 4 in. square, 2 ft. in ground for Cor. to Secs. 21-22 27 and 28.

Pine, 10 in. dia. N 60° W 132 lks.
Pine, 30 in. dia. S 86° W 53 lks.
Pine, 12 in. dia. S 35° E 37 lks.
Pine, 20 in. dia. N 56° E 105 lks.

Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner:

From which: an 11" P. Pine bears S14°E 58.9 ft. scribed T2S R36E S27 Bt

A 23" P. Pine bears N53°E 56.2 ft. scribed T2S R36E S 22 BT A 23" P. Pine bears N33°W 39.1 ft. scribed T2S R36E S 21 BT A 12" P. Pine bears S86°W 86.5 ft. scribed T2S R36E S 28 BT

Attached 54-3 and 54-4 signs to BT's painted blazes and 6" red ring around BT's. Attached brass washers LS 1099 to foot blazes. Set metal post 5' north of corner with 54-4 sign.

Corner falls on south edge of large clearing and 32 ft. north of dirt road.

Compass Declination: 18 1/2° East

I hereby certify the above described corner monument and/or accessories was established as described on November 17, 1981.

Witnesses: Jeff Anderson Greg Orton

| LAND SURVEYOR |
|-----------------------------------------------|
| Harn S. Sanglit |
| OREGON O JULY 22, 1977 GARY L. LANGLITZ |
| 1099 |

File No. 303-84R

REGISTERED

1981


OR PLS 1099

| Office of Surveyor County of Union State of Oregon I hereby certify that the within instrument was filed in to | his office |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|
| HOWARD L. PERRY by James J. Jong J. Jong J. Jong J. Jong J. John J. J. John J. J. John J. | UNION COUNTY SURVEYOR |
| orm R6-7100-57 (9/71) | Date Received |
| | Date Filed |
| | Ву |

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

| RECOVERED BY Matthew Faulkner, Oregon PLS | COORDINATE SYSTEM, ZONE, & UNIT United States/NAD83, Oregon North 3601, International foot | |
|--------------------------------------------|---------------------------------------------------------------------------------------------|------------|
| | | |
| 400300 | 628773.30 | 8766342.59 |
| LATITUDE | LONGITUDE | |
| N45°22'13.151" | W118°18'14.577" | |

T02S R36E R-13



RECORD OF ORIGINAL CORNER AND SUBSEQUENT HISTORY:

Record No. 1: The cor. of secs. 21, 22, 27 and 28, was established and described in the original field notes of the subdivisional lines of T. 02 S., R. 36 E., Willamette Meridian, Oregon, executed by Deputy Surveyor John A. Hurlburt in 1874 under Contract Number 201. Description: Set pine post, 4 ft. long, 4 ins. square, 2 ft. in ground, for cor. to secs. 21-22-27-28.

Pine 20 in. dia. N. 56° E., 105 lks.

Pine 12 in. dia. S. 35° E., 37 lks.

Pine 30 in. dia. S. 86° W., 53 lks.

Pine 10 in. dia. N. 60° W., 132 lks.

Record No. 2: Certified Record of Land Corner Monumentation, on file with the Union County Land Surveyor's Office. By Gary L. Langlitz, Oregon Professional Land Surveyor No. 1099. Recorded on October 4, 1982, File No. 303-84R. Description: Corner location determined by survey and double proportionate measurement procedures: At surveyed point set 2 1/2" x 30" galvanized pipe with brass cap attached 12" in the ground stamped: with mound of stone and dirt to cap.

From which: (Note: These are new BTs added by Mr. Langlitz as he did not recover any of the original 1874 BTs)

- A Ponderosa Pine, 23 ins. dia., bears N. 53° E., 56.2 ft. dist., scribed T2S R36E S 22 BT.
- A Ponderosa Pine, 11 ins. dia., bears S. 14° E., 58.9 ft. dist., scribed T2S R36E S 27 BT.
- A Ponderosa Pine, 12 ins. dia., bears S. 86° W., 59.1 ft. dist., scribed T2S R36E S 28 BT.
- A Ponderosa Pine, 23 ins. dia., bears N. 33° W., 39.1 ft. dist., scribed T2S R36E S 21 BT.

Attached 54-3 and 54-4 signs to BT's painted blazes and 6" red ring around BT's. Attached brass washers LS 1099 to foot blazes. Set metal post 5' north of corner with 54-4 sign. Corner falls on south edge of large clearing and 32 ft. north of dirt road.

DESCRIPTION OF CORNER EVIDENCE FOUND AND DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE LOCATION OF THIS CORNER:

Recovery Date: 10/22/2023

Description: The cor. of secs. 21, 22, 27 and 28, monumented with an iron post, 2 1/2 ins. diam., firmly set, projecting 12 ins. above the top of a mound of stone, 2 1/2 ft. base, 1 ft. high, with brass cap mkd. as shown below on this corner record and in the 1975 cadastral field notes.


from which the 1982 bearing trees:

- A Ponderosa Pine, 24 ins. dia., bears S. 82° E. (Record: N. 53° E.), 56.2 ft. dist., with the scribe marks SR36ES22BT visible on a partially healed blaze, with a brass washer marked LS 1099 nailed to the blaze.
- A Ponderosa Pine, 15 ins. dia., bears S. 14° E., 58.9 ft. dist., mkd. T2SR36ES27BT on a partially healed blaze, with a brass washer marked LS 1099 nailed to the blaze.
- A Ponderosa Pine, 16 ins. dia., bears S. 86° W., 59.1 ft. dist., with the scribe marks SR36ES28BT visible on a partially healed blaze, with a brass washer marked LS 1099 nailed to the blaze.

The downed and decayed remains of a Ponderosa Pine, size indeterminable, bears N. 33° W., 39.1 ft. dist., with illegible scribe marks visible in the decayed blaze.

Rebuilt the mound of stone surrounding the iron post monument to now be 4 ft. base, to top of the brass cap. Set a carsonite post, N., approximately 4 ft. dist., from the monument. Painted the blazes with red spray paint.

CERTIFIED RECORD OF LAND CORNER MONUMENTATION







The SW 1982 BT:



The NW 1982 BT:



UNION COUNTY SURVEYOR Date Received 12/22/23 12/22/23 File No. 061-2023R

REGISTERED **PROFESSIONAL** LAND SURVEYOR

OREGON JUNE 08, 2009 MATTHEW J. FAULKNER 75618LS

RENEWS: 12/31/25