

CERTIFIED RECORD OF LAND CORNER MONUMENTATION


Index File No. R-15

History of original corner establishment:

John A. Hurlbert in 1874 under G.L.O. contract No. 201 set a Pine post 4 ft. long 3" thick 2' in the ground for 1/4 Sec. Cor. from which:

A Pine 24" in dia. bears S19°W 54 lks.

A Pine 12" in dia. bears N15°E 110 lks.



Description of corner evidence found:

The original N.E. bearing tree, a found 22" Ponderosa Pine alive with opened blaze and visible scribing " 1/4". At location of corner found remains of rotted Pine post. No signs of SW BT, which falls in a power line right-of-way.

Description of monument and accessories I established to perpetuate the original location of this corner:

At the true corner point established by reference to the original NE bearing tree, we set a 2 1/2" by 30" galvanized pipe 20" in the ground with 3" brass cap stamped:

From which: A Pine 12" dia. bears N 31°E 81.6 ft. scribed "1/4 S 22 BT"

A Pine 14" dia. bears S55°E 46.2 feet scribed 1/4 S27 BT. Painted blazes and 6" band around trees red. Attached 54-4 and 54-3 signs to both BT's. Attached brass washer stamped LS 1099 to foot blaze of both BT's. Attached 54-4 sign to metal fence post set 6' West of corner.

T2S	R36E
	S22
1/4	—+—
	S27
	1981
	PLS 1099

Compass Declination: 18 1/2° E

I hereby certify the above described corner monument and/or accessories was established as described on June 17, 1981.

Witnesses: Glen Wagoner
Millard Wyatt

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Gary L. Langlitz
OREGON
JULY 22, 1977
GARY L. LANGLITZ
1099

Office of..... Surveyor..... County of..... Union.....
State of..... Oregon..... I hereby certify that the within instrument was filed in this office
for record on the... 4... day of... OCTOBER..... 1982.....
..... Howard L. Perry..... by *Gary L. Langlitz*.....
(COUNTY OFFICIAL) (DEP. SURV.)

UNION COUNTY SURVEYOR	
Date Received	_____
<small>GPO 799-509</small>	
Date Filed	_____
By	_____
File No.	<u>304-84R</u>