


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:
Corner not previously established.



No record of subsequent monumentation found in Union County survey records.

Description of corner evidence found:
Corner not previously established.
See map of survey dated June, 1989.

**UNION COUNTY
SURVEYOR**


Date Received 8-22-89
Date Filed 8-22-89
By G. LANGLITZ, DEPUTY
File No. 145-89 R

Description of monument and accessories | established to perpetuate the
original location of this corner: At position determined by survey, I set a 2½" x 30" aluminum
pipe with aluminum cap marked as shown, 28 inches in the ground, from which:

New BTs:
A 7 inch diameter Ponderosa Pine bears N10°E, 4.81 feet marked X BT
A 10 inch diameter Douglas Fir bears S57°E, 20.52 feet marked NW 1/16 S26 BT

Painted a 6 inch red band around all BTs and attached
bearing tree and land survey monument signs.
Set a steel fencepost approximately 5 feet North with
land survey monument and property boundary signs attached.
Raised a mound of stone around monument, 3 ft. base to top of cap.

I hereby certify that the above corner point was
perpetuated as hereon described on June 11, 1989.



I used a steel tape and magnetic compass in the
establishment of new accessories. I used 17°
East magnetic declination and the distances are
to a 50d spike driven in the right side of the
root crown. I attached a brass washer marked
OPLS 644 to the BT blaze.

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19.....
..... by

(COUNTY OFFICIAL) (DEPUTY)