

14-70A

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

T-5

History of original corner establishment:

Corner established by General Land Office contract survey

The original notes state:


North between Sections 29 and 30

40.00 Set pine post 4 ft. long 3 in. thick, 2" in ground for $\frac{1}{4}$ section corner.

Fir 18" dia S74°W 19 lks marked $\frac{1}{4}$ SBT;

Fir 10" dia S33°E 31 lks marked $\frac{1}{4}$ SBT;

54.00 Stream 10 lks wide runs SE.



Description of corner evidence found:

In Section 29, found down log with scribe S33°E.

Description of monument and accessories I established to perpetuate the original location of this corner

At the position of the corner I set a 30" galvanized pipe with an eight inch plate welded on bottom and a bronze cap on top. The hole was back filled with stone and tamped soil.

I stamped the disk.

From the monument the original bearing trees were (none). I established the following new bearing trees:

Fir 9" dia S61°W at a distance of 31.7 ft. and scribed $\frac{1}{4}$ S BT;

Fir 8" dia N35°E at a distance of 23.7 ft. and scribed $\frac{1}{4}$ S BT;

The distance measured to center of respective trees on level. I placed bearing tree signs on both old and new bearing trees and painted stripe around trees. I placed a steel fence post with USFS sign 54-4 attached near the corner.

$\frac{1}{4}$ COR
T2S R36E
330 329
ORE LIC 381
1970

Office of.....County Surveyor..... County of..... Union.....

State of.....Oregon....., I hereby certify that the within instrument was filed in this office

for record on the 23 day of July, 1970, at 3 o'clock P.m. (initials)

County Surveyor

(COUNTY OFFICIAL)

by James H. [Signature] (DEPUTY)

UNION COUNTY SURVEYOR

Date Received _____

Date Filed _____

By _____

File No. 306-84 R