

CERTIFIED RECORD OF LAND CORNER MONUMENTATION


History of original corner establishment:

Corner established by Henry Meldrum under GLO contract no. 450 dated June 11, 1882.

Surveyor General records state:

Set post 3 ft long 3 ins square 24 ins in the ground for 1/4 sec corner marked 1/4 on N face from which;

A pine 12 ins diam bears S 06° W, 23 lks dist marked 1/4 S BT
A fir 6 ins diam bears N 03° E 28 lks dist marked 1/4 S BT



Description of corner evidence found:

NONE, corner position remonumented at proportionate distance between the found Northeast and Northwest corners of section 12.

Description of monument and accessories established to perpetuate the original location of this corner:

Set a 2 1/2 inch brass cap on a 2 inch iron pipe 31 inches long and projecting 5 inches out of the ground with a surrounding rock mound and a 6 foot steel fence post alongside with a sign 54-4 attached.

Brass cap marked thus:

T 2 S R 37 E

$\frac{1}{4}$ $\frac{S}{S} \frac{1}{12}$

1983

ORLS 1639

New bearing trees established:

A spruce 14 ins diam bears N 40° W, 9.7 feet dist marked 1/4 S 1 BT
A tamarack 8 ins diam bears S 06° W, 9.2 feet dist marked 1/4 S 12 BT

Each new bearing tree has a sign 54-3 attached below a 6 inch band of red paint and a brass washer marked PLS 1639 nailed flush with BT blaze. A sign 54-4 is attached on opposite side of tree from BT blaze.

I hereby certify that the above described corner monument was properly established by me on Oct. 18, 1983, and witnessed by Jim DeMastus.

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

William L. Hanley

OREGON
JULY 14, 1978
WILLIAM L. HANLEY
1639

Office of County Surveyor County of Union
Oregon

State of Oregon I hereby certify that the within instrument was filed in this office
for record on the day of 19

..... by
(COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY
SURVEYOR**

Date Received 11-10-83
Date Filed 11-14-83
By G. LANGLITZ DEPUTY
File No. 405-83 R