CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established by Henry Meldrum under GLO contract no. 450 dated June 11, 1882.

Surveyors General records state:

Set basalt stone $15 \times 10 \times 4$ ins 10 ins in the ground for cor to Secs 8, 9, 16 & 17 marked with 4 notches on S and 4 on E edges from which;

DIAGRAM T 2 S R 37 E S 8 S 9 S 17 S 16

A pine 8 ins diam bears N 29° W, 11 1ks dist marked T 2 S S 8 BT. A fir 24 ins diam bears S 48° W, 66 1ks dist marked S 17 BT. A pine 50 ins diam bears S 52° E, 82 1ks dist marked S 16 BT.

A pine 10 ins diam bears N 68° E, 62 1ks dist marked R 37 E S 9 BT.

Description of corner evidence found:

Found a sawed pine stump 50 ins diam for Section 16 bearing tree with T scribe.

Found a windblow fir 26 ins diam for Section 17 bearing tree with S 17 BT scribe marks.

Found a rotten root hole for Section 8 bearing tree.

No trace of Section 9 bearing tree.

At record bearing and distance from the original bearing trees, found a mound of stone and the original stone with 4 notches on south face and 2 definite notches on the east face.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a $2\frac{1}{2}$ inch aluminum cap on a 2 inch aluminum pipe 30 inches long 26 inches in the ground with 4 inches projecting out of the ground with a surrounding rock mound and a 6 foot steel fence post alongside with a sign 54-4 attached. Buried original stone on north side of monument.

Aluminum cap marked thus:

ORLS 1639

New bearing trees:

A fir 8 ins diam bears S 09° W, 12.8 feet dist marked T 2 S R 37 E S 17 BT.

A fir 8 ins diam bears S 51° E, 27.6 feet dist marked T 2 S R 37 E S 16 BT.
A pine 14 ins diam bears N 77° E, 67.0 feet dist marked T 2 S R 37 E S 9 BT.
A tamarack 8 ins diam bears N 46° W, 17.5 feet dist marked T 2 S R 37 E S 8 BT.

Each new bearing tree has a sign 54-3 nailed below a 6 inch band of red paint and a brass washer marked PLS 1639 nailed flush with BT blaze and a sign 54-4 nailed on opposite side of tree from BT blaze.

I hereby certify that the above corner monument was properly established by me on Aug. 31, 1983, and witnessed by Jim DeMastus.

REGISTERED **PROFESSIONAL** LAND SURVEYOR

William L'Hanler Office of...... County Surveyor Union OREGON JULY 14, 1978 WILLIAM L. HANLEY for record on the...... day of...... , 19..... by UNIPH COUNTY

1639

(COUNTY OFFICIAL)

Form R6-7100-57 (9/71)

Date Received 9-6-83

SURVEYOR

☆ GPO---798-276