CERTIFIED RECORD OF LAND CORNER MONUMENTATION

CORNER MAINTENENCE


History of original corner establishment:

Corner established by Henry Meldrum under GLO contract no. 450 dated June 11, 1882.

Surveyor General records state:

Set basalt stone $18 \times 15 \times 10$ ins 12 ins in the ground for $\frac{1}{4}$ Sec Corner marked 1/4 on W face from which:

A pine 24 ins diam bears N 32° W, 36 1ks dist marked 1/4 S BT. A pine 5 ins diam bears N 49° E, 12 1ks dist marked 1/4 S BT.



This corner was remonumented by Anderson-Perry & Associates in 1977 with a 3 inch brass cap on a 2 inch iron pipe. No new bearing trees established.

Description of corner evidence found:

Found a 3 inch brass cap on a 2 inch iron pipe flush with the ground marked thus:

.

Found a broken pine snag marked l / S B for section 13 bearing tree. Original section 14 bearing tree was positioned in roadway and no trace found.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 6 foot steel fence post alongside brass cap monument with sign 54-4 attached and built a mound of stone around.

New bearing trees established:

Form

A fir 9 ins diam bears N 57° E, 9.9 feet dist marked 1/4 S 13 BT A fir 7 ins diam bears N 33° W, 15.8 feet dist marked 1/4 S 14 BT.

Each new bearing tree has a sign 54-3 attached below a 6 inch band of red paint and a brass washer marked PLS 1639 nailed flush with BT blaze. A sign 54-4 is attached on opposite side of tree from BT blaze.

I hereby certify that the above described corner monument was maintained to Forest Service standards by me on Sept. 7, 1983, and witnessed by Jim DeMastus.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

WILLIAM L. HONLY
1639

Office ofCountySurveyor	ounty ofUnionthe within instrument was filed in a	this office
for record on the day of , 19 , 19 by		UNION COUNTY
(COUNTY OFFICIAL)	(DEPUTY)	
6-7100-57 (9/71)		Date Received 9-28-83
		Date 5144 9-78-83