


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not previously established.



No record of subsequent monumentation found in Union County survey records.

Description of corner evidence found:

Corner not previously established

See map of survey dated November, 1989.

Description of monument and accessories I established to perpetuate the

original location of this corner: At position determined by survey, I set a 2½" x 30" aluminum pipe with aluminum cap marked as shown, 20 inches in the ground, from which:

New Bearing Trees:


A 9 inch diameter Ponderosa Pine bears N25°E, 74.75 feet marked S1/16 S16 BT
A 12 inch diameter Ponderosa Pine bears N56°W, 28.23 feet marked S1/16 S17 BT

Raised a mound of stone around monument, 2 ft. base to top of cap.

Painted a 6 inch red band around all BTs and attached bearing tree and land survey monument signs.

Set a steel fencepost approximately 5 feet East with land survey monument and property boundary signs attached.

I hereby certify that the above corner point was perpetuated as hereon described on October 17, 1989.



REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 10, 1954
DUANE I. GRIFFITH
644

I used a steel tape and magnetic compass in the establishment of new accessories. I used 17° East magnetic declination and the distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 644 to the BT blaze.

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

(COUNTY OFFICIAL) **UNION COUNTY SURVEYOR** (DEPUTY)

Form R6-7100-57 (9/71)

Date Received 12-27-89
 Filed 12-27-89
 BY RUBEN W. DEPUTY
 File No. 259 89R

★ U.S. GOVERNMENT PRINTING OFFICE - 1983-793-276

M-09