


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not previously established.



No record of subsequent monumentation found in Union County survey records.

Description of corner evidence found:

Corner not previously established

See map of survey dated November, 1989.

Description of monument and accessories I established to perpetuate the

original location of this corner: At position determined by survey, I set a 2½" x 30" aluminum pipe with aluminum cap marked as shown, 27 inches in the ground, from which:

New Bearing Trees;


A 10 inch diameter Western Larch bears N65°W, 42.64 feet marked CS1/16 S16 BT
A 8 inch diameter Western Larch bears N11°W, 36.94 feet marked X BT

Painted a 6 inch red band around all BTs and attached bearing tree and land survey monument signs.

Set a steel fencepost approximately 5 feet North with land survey monument and property boundary signs attached.

I hereby certify that the above corner point was perpetuated as hereon described on October 19, 1989.

Witnesses: Rick Robinson and Jeff Petersen



REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JULY 10, 1964
DUANE I. GRIFFITH
644

I used a steel tape and magnetic compass in the establishment of new accessories. I used 17° East magnetic declination and the distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 644 to the BT blaze.

Office of..... County of.....

State of..... I hereby certify that the within instrument was filed in this office

for record on the..... day **UNION COUNTY**, 19.....

.....
(COUNTY OFFICIAL) SURVEYOR (DEPUTY)

Form R6-7100-57 (9/71)

Date Received 12-27-89

Date Filed 12-27-89

By R. Robinson Deputy

File No. 258 805

☆ U.S. GOVERNMENT PRINTING OFFICE - 1983-793-276

M-11