


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:  
Corner was not originally set.



No record of subsequent monumentation found in Union County survey records

Description of corner evidence found:

See map of survey dated June 1992.

Description of monument and accessories I established to perpetuate the original location of this corner:

At the corner position, determined by survey, I set a 2 1/2"x30" aluminum pipe with aluminum cap marked as shown, 28 inches in the ground, from which:

New Bearing Trees;

A 10 inch diameter Douglas fir bears N18°E, 17.10 feet marked C N 1/16 BT


A 22 inch diameter Ponderosa pine bears S70°E, 26.47 feet marked C N 1/16 BT

Raised small mound of stone.

Set a steel fence post approximately 5 feet South with Attention and property boundary sign attached.

I hereby certify that the above corner point was perpetuated as hereon described on June 2, 1992.

Witness: Peter Crabtree  
G.T. Blackman



REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

OREGON  
JULY 10, 1964  
DUANE I. GRIFFITH  
644

I used a steel tape and magnetic compass in the establishment of new accessories. I used 17° East magnetic declination and the distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 644 to the BT blaze

Office of..... County of.....  
State of....., I hereby certify that the within instrument was filed in this office  
for record on the..... day of.....

(COUNTY OFFICIAL)

19  
by [Signature] (DEPUTY)  
Date Received 9/15/92  
Date Filed 9/15/92  
By Gregory T. Black  
File No. 067-1992R

Form R6-7100-57 (9/71)

•GPO-591-971, 1988