
History of original corner establishment:

Corner not previously established.



No record of subsequent monumentation found in Union County survey records.

Description of corner evidence found:

Corner not previously established

See map of survey dated November, 1989.

Description of monument and accessories I established to perpetuate the

original location of this corner: At the proportionate position between the section corners North and South; I set a  $2\frac{1}{2}$ " x 30" aluminum pipe with aluminum cap marked as shown, 22 inches in the ground, from which:


New Bearing Trees and Bearing Object;
A 23 inch diameter Ponderosa Pine bears N85°E, 105.65 feet marked X BT
A 5/8"x30" iron pin with plastic cap marked BGA SURVEY MARKER bears S43°E, 16.00 feet.
A 10 inch diameter Ponderosa Pine bears N39°E, 117.06 feet marked F BT
A 15 inch diameter Ponderosa Pine bears N13°E, 81.53 feet marked \$ S19 BT
Painted a 6 inch red band around all BTs and attached
bearing tree and land survey monument signs.
Set a steel fencepost approximately 5 feet
North with land survey monument sign attached.

Raised a mound of stone around monument, 3 ft. base to top of cap.

I hereby certify that the above corner point was perpetuated as hereon described on October 25, 1989.

Witnesses: Jeff Petersen and Rick Robinson

REGISTERED PROFESSIONAL AND SURVEYOR DREGON 1 DUANE I. GRIFFITH



I used a steel tape and magnetic compass in the establishment of new accessories. I used 17° East magnetic declination and the distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 644 to the BT blaze.

Office of	County	of
		ithin instrument was filed in this office
for record on the	dey Which County	9
COUNT	OFFICIAL)	(DEPUTY)
Form R6-7100-57 (9/71)	Data Received 12-27-89	☆U,S, GOVERNMENT PRINTING OFFICE -1983-793-276
	Date Filed 12-27-89	
	By R. ROPHUSON, DENTY	P-01
	File No. 250 898	

2-4