


History of original corner establishment:

Corner not previously established.



No record of subsequent monumentation found in Union County survey records.

Description of corner evidence found:

Corner not previously established

See map of survey dated November, 1989.

Description of monument and accessories I established to perpetuate the

original location of this corner: At position determined by survey, I set a 2 1/2" x 30" aluminum pipe with aluminum cap marked as shown, 26 inches in the ground, from which:

New Bearing Tree and Bearing Object;

A 1/2"x30" iron pin with plastic cap marked BGA MARKER bears N20°E, 5.71 feet.

A 13 inch diameter Ponderosa Pine bears N50°W, 110.88 feet marked SW1/16 S19 BT


Painted a 6 inch red band around the BT and attached bearing tree and land survey monument signs.

Set a steel fencepost approximately 5 feet South with land survey monument and property boundary signs attached.

Raised a mound of stone around monument, 3 ft. base to top of cap.

I hereby certify that the above corner point was perpetuated as hereon described on November 10, 1989.

Witnesses: Jeff Petersen and Rick Robinson



REGISTERED PROFESSIONAL LAND SURVEYOR

[Signature]

OREGON JULY 10, 1984 DUANE I. GRIFFITH 644

I used a steel tape and magnetic compass in the establishment of new accessories. I used 17° East magnetic declination and the distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 644 to the BT blaze.

Office of..... County of.....

State of....., I hereby certify that the within instrument was filed in this office

for record on the..... day of....., 19.....

UNION COUNTY SURVEYOR (COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

Date Received 12-27-89
 Date Filed 12-27-89
 By P. ROBINSON DEPUTY
 File No. 246 B9R