


History of original corner establishment:  
Corner not previously established.



No record of subsequent monumentation found in Union County survey records.

Description of corner evidence found:

Corner not previously established

See map of survey dated November, 1989.

Description of monument and accessories I established to perpetuate the

original location of this corner: At position determined by survey, I set a 2½" x 30" aluminum pipe with aluminum cap marked as shown, 28 inches in the ground, from which:


New Bearing Trees:

- A 22 inch diameter Douglas Fir bears N40°E, 4.07 feet marked NE1/16 S30 BT
- A 12 inch diameter Douglas Fir bears N30°W, 10.1 feet marked X BT

Painted a 6 inch red band around all BTs and attached bearing tree and land survey monument signs.

Set a steel fencepost approximately 5 feet North with land survey monument and property boundary signs attached.

I hereby certify that the above corner point was perpetuated as hereon described on October 28, 1989.



REGISTERED PROFESSIONAL LAND SURVEYOR

*Duane I. Griffith*  
 OREGON  
 JULY 10, 1964  
 DUANE I. GRIFFITH  
 644

I used a steel tape and magnetic compass in the establishment of new accessories. I used 17° East magnetic declination and the distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 644 to the BT blaze.

Office of..... County of.....  
 State of..... I hereby certify that the within instrument was filed in this office  
 for record on the..... day of..... 19.....

UNION COUNTY SURVEYOR

(COUNTY OFFICIAL)

(DEPUTY)

Date Received 12-27-89

Date Filed 12-27-89

By P. Robinson, Deputy

File No. 747 89E

Form R6-7100-57 (9/71)

☆ U.S. GOVERNMENT PRINTING OFFICE - 1983-793-276