


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

None.

T 2 S R 37 E S-15



DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

SEE SURVEY NUMBER 006-2019

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At the position by survey I set a 5/8"x30" iron pin 26" in the ground with 2 1/2" aluminum cap marked as shown below, from which:

NEW BEARING TREES:

A 13" Douglas Fir bears North 55° East a dist. of 5.00 ft., marked CN 1/16 S27 BT.
A 7" White Fir bears North 32° West a dist. of 5.65 ft., marked CN 1/16 S27 BT.


Set steel fence post approx. 1 ft. South

I hereby certify that the corner was monumented on April 25, 2019.

Witness: Kyle A. Tucker.



Renewal Date: June 30, 2019



UNION COUNTY SURVEYOR	
Date Received	5/14/19
Date Filed	5/14/19
Filed By	<i>[Signature]</i>
File Number	021-2019R

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 13° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. The bearings are to a brass washer marked OPLS 83571 attached to the BT blaze of the new bearing trees.