
History of original corner establishment:

Corner not previously established.



No record of subsequent monumentation found in Union County survey records.

Description of corner evidence found:

Corner not previously established
See map of survey dated November, 1989.

Description of monument and accessories I established to perpetuate the

original location of this corner: At position determined by survey, I set a $2\frac{1}{2}$ " x 30" aluminum pipe with aluminum cap marked as shown. 29 inches in the ground, from which:


New Bearing Trees:
A 12 inch diameter Ponderosa Pine bears N51°E. 36.15 feet marked X BT
A 8 inch diameter Ponderosa Pine bears S37°E. 70.0 feet marked X BT
A 15 inch diameter Ponderosa Pine bears N6°W. 28.06 feet marked C¼ S30 BT
A 12 inch diameter Douglas Fir bears N73°W. 51.46 feet marked C¼ S30 BT

Painted a 6 inch red band around all BTs and attached bearing tree and land survey monument signs.

Set a steel fencepost approximately 5 feet North with land survey monument and property boundary signs attached.

I hereby certify that the above corner point was perpetuated as hereon described on November 10, 1989.

Witnesses: Jeff Petersen and Rick Robinson



PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 10, 1984

DUANE I. GRIFFITH
644

I used a steel tape and magnetic compass in the establishment of new accessories. I used 17° East magnetic declination and the distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 644 to the BT blaze.

State of			
	WHICH COUNTY SURVEYOR		
(COUNTY OFFICIAL)		(DEPUTY)	
Form R6-7100-57 (9/71)	Dato Received 12-27-89		•GPO-591-971, 1988
2-16	Dola Filad 27, 60	T -03	
	BY R. POBLIFORD DEPOTY		
	File No. 230 82B		