


History of original corner establishment:
Corner not previously established.



No record of subsequent monumentation found in Union County survey records.

Description of corner evidence found:

Corner not previously established

See map of survey dated November, 1989.

Description of monument and accessories I established to perpetuate the

original location of this corner: At position determined by survey, I set a 2 1/2" x 30" aluminum pipe with aluminum cap marked as shown, 20 inches in the ground, from which:

New Bearing Trees:

- A 12 inch diameter Ponderosa Pine bears S37°E, 32.46 feet marked CE1/16 S30 BT
- A 9 inch diameter Douglas Fir bears S47°W, 42.07 feet marked CE1/16 S30 BT


Painted a 6 inch red band around all BTs and attached bearing tree and land survey monument signs.

Set a steel fencepost approximately 5 feet North with land survey monument and property boundary signs attached.

Raised a mound of stone around monument, 4 ft. base to top of cap.

I hereby certify that the above corner point was perpetuated as hereon described on November 10, 1989.

Witnesses: Jeff Petersen and Rick Robinson



REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JULY 12, 1984 DUANE I. GRIFFITH 644

I used a steel tape and magnetic compass in the establishment of new accessories. I used 17° East magnetic declination and the distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 644 to the BT blaze.

Office of..... County of.....

State of..... I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

UNION COUNTY SURVEYOR by R. ROBINSON, DEPUTY Date Received 12-27-89 Date Filed 12-27-89 File No. 238-89R

Form R6-7100-57 (9/71)

U.S. GOVERNMENT PRINTING OFFICE - 1983-793-276