CERTIFIED RECORD OF LAND CORNER MONUMENTATION




Corner established by Henry Meldrum under GLO contract no. 450 dated June 11, 1882.

Surveyor General records state:

Set basalt stone $16 \times 10 \times 6$ ins 11 ins in the ground for $\frac{1}{4}$ Sec Corner marked 1/4 on W face and raised mound of stone alongside

A pine 12 ins diam bears N 70° W, 79 lks dist marked 1/4 S BT.



Description of corner evidence found:

A 30 inch diameter pine for section 30 bearing tree with 1/4 S scribes visible in partially healed blaze.

Found a rock mound at record position form original bearing tree but failed to identify original stone.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a $2\frac{1}{2}$ inch brass cap on a 2 inch galvanized iron pipe 31 inches long 27 inches in the ground with 4 inches projecting out of the ground with a surrounding rock mound and a 6 foot steel fence post alongside with a sign 54-4 attached.

Brass cap marked thus:

T 2 S R 37 E
$$\frac{1}{4}$$
 S 30 S 29 1983

ORLS 1639

New bearing tree:

A pine 10 ins diam bears N 75° E, 34.1 feet dist marked 1/4 S 29 BT and has a sign 54-3 nailed below a 6 inch band of red paint and a brass washer marked PLS 1639 nailed flush with BT blaze and a sign 54-4 nailed on opposite side of tree from BT blaze.

I hereby certify that the above described monument was properly established by me on Aug. 30, 1983, and witnessed by Jim DeMastus.

REGISTERED **PROFESSIONAL** LAND SURVEYOR William L. Hanley OREGON JULY 14, 1978 WILLIAM L. HANLEY 1639

Office of County Surveyor Co	Union Union	
State of Oregon , I hereby certify that	the within instrument was filed in this	office
for record on the day of , 19 , 19		UNION COUNTY
(COUNTY OFFICIAL)	(DEPUTY)	SURVEYOR
R6-7100-57 (9/71)		0 t Poceived 9-6-83

Form F