
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

This corner was not set in the original survey.



No record of subsequent monumentation found in Union County survey records **DESCRIPTION OF CORNER EVIDENCE FOUND:**

NONE

See Union County Survey Number 027-1993.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position, determined by survey I set a $2\frac{1}{2}$ " x 30" aluminum pipe with aluminum cap marked as shown, 22 inches in the ground, from which;

BEARING TREES


A 25" White Fir bears S 33°E, 43.73 feet, marked X BT A 25" Douglas Fir bears N 47°W, 30.42 feet, marked CS1/16 S25 BT

Raised a small mound of stone around monument to top of cap.

I hereby certify that the above corner point was perpetuated as hereon described on August 2, 1993.

Witness

Jim Bennett Travis Foster



REGISTERED PROFESSIONAL LAND SURVEYOR

I used a steel tape and magnetic compass in the establishment of new accessories. I used 17° East magnetic declination and the distances are

DUANE I. GRIFFITH 644

File No. 029-1993

U-23