RESTORED CORNERS

Section 31, Township 2 South, Range 37 East W. M.

Hilgard Junction State Park

Union County

August 28, 1969

Var 20°

SECTION CORNER 5, 6, 31 and 32

ORIGINAL:

Post and mound of stone (found rotted post and mound of stone and Forest Service tag dated 1947)

RESTORED:

19" Pine S15°W 34.8 ft. scribed, "T3SR37ES6BTRS691"
18" Pine S63°W 82.8 ft. scribed, "T3SR37ES6BT"
18" Pine N1°W 87.4 ft. scribed, "T2SR37ES31BT"

No trees available in other sections. Yellow corner tag on 19" BT.

Witnessed by: A. Slack

R. Hemmer

T. Stose

SECTION CORNER 29, 30, 31 and 32

ORIGINAL:

Stone and mound (found stone out of place) 15" Pine S31°W 105 LKS. (now 24" stump, scribe visible)

RESTORED:

Reset stone from PT. Erected mound of stone around cornerstone.
Pine N75°W 111.2 ft. scribed, "T2SR37ES30BTRS691" Yellow corner tag on new Pine BT. Another mound of stones bears South 6 ft.

Witnessed by: A. Slack

R. Hemmer

T. Stose

1 CORNER 30 and 31

ORIGINAL:

Stone (found out of place) 12" Pine N41°E 21 LKS. (now 12" stump, "BT" visible)
12" Pine S30°E 25 LKS. (now missing)

RESTORED:

Set original stone in place. Erected mound of stone around cornerstone. Set 4" x 4" x 48" white post 1 ft. South of corner. 10" Pine S79°W 6.3 ft. scribed, "\frac{1}{4}S31BTRS691"
10" Pine N36°E 23.2 ft. scribed, "\frac{1}{4}S30BT"

Witnessed by: J. Hollingsworth E. Haury

R. Hemmer

T. Stose

(WORK PERFORMED IN 1969)
G. LANGLITZ DEP. CO. SURVEYOR

UNION COUNTY **SURVEYOR**

File No. 316-84R

UNION COUNTY SURVEYOR

Date Received

Date Filed

Date Received_	
Date Filed	
Ву	

TZS R37E)

UNION COUNTY **SURVEYOR**

Date Received_

Date Filed_

E. Hollingswell

File No. 318-84R

REGISTERED OREGON LAND SURVEYOR

JULY 9, 1965 John E. Hollingsworth 691

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established by John A. Hurlburt under GLO contract no. 201 dated August 5, 1873.

Surveyor General records state:

Set basalt stone $18 \times 14 \times 6-8$ ins in ground and made stone mound 2 ft high for 1/4 sec cor

Pine 12 in dia N 41° E, 21 1ks Pine 12 in dia S 30° E, 25 1ks DIAGRAM

T 2 S R 37 E

1 S 30
3 S 31

Description of corner evidence found:

A rotten laid over stump for original Section 30 bearing tree with BT scribes visible. Found stone of record size in stone mound but did not identify any chisle work.

Found a 4" x 4" x 48" wood post in place and set by John E. Hollingsworth for quarter corner in east-west running fence line.

Bearing trees established by Hollingsworth:

A pine 11 ins diam bears S 87° W, 5.5 ft dist marked 1/4 S 31 BT RS 691 on partially healed blaze.

A pine 13 ins diam bears N 37° E, 25.5 ft dist with partially healed and pitched over blaze, no scribes readable.

Description of monument and accessories Lestablished to perpetuate the original location of this corner:

At position of 4" x 4" x 48" wood post set a $2\frac{1}{2}$ inch brass cap on a 2 inch iron pipe 31 inches long and projecting 5 inches out of the ground with a surrounding rock mound and a 6 foot steel fence post alongside with a sign 54-4 attached.

Brass cap marked thus:

T 2 S R 37 E

 $\frac{1}{4} \qquad \frac{\text{S} \quad 30}{\text{S} \quad 31}$

1983

ORLS 1639

To existing bearing trees established by Hollingsworth and original bearing tree stump attached sign 54-3 and 54-4 and painted 6 inch band of red paint around.

I hereby certify that the above described corner monument was properly established by me on Nov. 4, 1983, and witnessed by Jim DeMastus.

REGISTERED PROFESSIONAL LAND SURVEYOR William L. Hanley JULY 14, 1978 WILLIAM L. HANLEY 1639

Office of County Surveyor	County of. Union
State of Oregon I hereby certi	fy that the within instrument was filed in this office
for record on the day of	
***************************************	by
(COUNTY OFFIC(AL)	(DEPUTY)
R6-7100-57 (9/71)	

Form R6-7100-57 (9/71)

- 11110-03

Date Received 11-10-83

UNION COUNTY SURVEYOR

Date Filed 11-14-83

BY G. LANGLITZ DEPUTY

Ella No 388-83 R