
## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not previously established.



No record of subsequent monumentation found in Union County survey records.

## Description of corner evidence found:

Corner not previously established See map of survey dated January, 1989.

UNION COUNTY SURVEYOR	
Date Received Z~/3~89	
Date Filed <u>Z-/3-89</u>	
By G. LANGUIR DEPUTY	
File No. 38-89 R	

## Description of monument and accessories I established to perpetuate the

original location of this corner: At position determined by survey, I set a 2½" x 30" aluminum pipe with aluminum cap marked as shown, 26 inches in the ground, from which:

New BTs:

A 11 inch diameter Douglas Fir bears East, 9.69 feet marked C¼ S31 BT A 20 inch diameter Ponderosa Pine bears S11°W, 35.02 feet marked C¼ S31 BT

Painted a 6 inch red band around all BTs and attached bearing tree and land survey monument signs.

Set a steel fencepost approximately 5 feet North with property boundary and land survey monument sign attached.

Raised small mound of stone around monument.

I hereby certify that the above corner point was perpetuated as hereon described on December 21, 1988.

Witnesses: Greg Blackman and Rick Robinson



REGISTERED PROFESSIONAL LAND SURVEYOR	
du d Sigg	1.
OREGON JULY 10, 1994 DUANE I. GRIFFITH	•
644	

I used a steel tape and magnetic compass in the establishment of new accessories. I used 17° East magnetic declination and the distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 644 to the BT blaze.

Office of	County of	
State of / hereby certify th	et the within instrument was filed in this office	
for record on the day of		
by		
(COUNTY OFFICIAL)	(DEPUTY)	

Form R6-7100-57 (9/71)

☆ GPO---798-276