## **UNION COUNTY SURVEYOR**

## **CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:


Corner not previously established

## DESCRIPTION OF CORNER EVIDENCE FOUND:

No evidence of any recorded monuments. Found Unrecorded 3/4" pipe North 33°48'23" West, 21.03 feet from true corner position.

(See Survey Number 004-2007)

## T2S R38EB-10



DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by survey, I set a 5/8"x30" iron pin with a  $2\frac{1}{2}$ " aluminum cap marked as shown below, 30" in the ground from which:

A 31 inch diameter Douglas Fir bears North 89° East, a distance of 39.70 feet, marked NW  $1/16\ S4\ BT$ .

A 25 inch diameter Ponderosa Pine bears South 34° East, a distance of 49.85 feet, marked NW  $1/16~\rm S4~BT.$ 

I hereby certify that the corner was monumented on February 2, 2007. Witness: Jeff Hsu, Leo Castillo

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
July 17, 1986
RICK G. ROBINSON
2219

Renewal Date: December 31, 2008

GRIFFITH & SIN 1/16

T 2 S R 38 E

NW 1/16

S 4

2007

OPLS 2219

Date Filed Z/15/07

UNION COUNTY

File Number COL - 2007 R

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 18° East magnetic declination, with the distances to a 50d nail driven on the right side of the bearing tree. I attached a brass washer marked OPLS 2219 at the top of the BT Blaze.