


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established by T. W. Davenport under GLO contract no. 102 dated July 20, 1863.

Surveyor General records state:

Set qr. sec post from which:  
 A spruce 6 ins diam bears SE 1 lks.  
 A spruce 5 ins diam bears S 25° W, 10 lks.




Description of corner evidence found:

NONE: Corner is remonumented at single proportionate distance between the Northwest and Southwest corners of Section 6.

Description of monument and accessories established to perpetuate the original location of this corner:

Set a 2 1/2 inch brass cap on a 2 inch galvanized iron pipe 31 inches long 26 inches in the ground with 5 inches projecting out of the ground with a large surrounding rock mound and a 6 foot steel fence post alongside with a sign 54-4 attached.

Brass cap marked thus:



New bearing trees:

A fir 13 ins diam bears S 59° W, 29.4 feet dist marked 1/4 S 1 BT.  
 A fir 9 ins diam bears S 50° E, 9.0 feet dist marked 1/4 S 6 BT.

Each new bearing tree has a sign 54-3 nailed below a 6 inch band of red paint and a brass washer marked PLS 1639 nailed flush with BT blaze with a sign 54-4 nailed on opposite side of tree from BT blaze.

I hereby certify that the above described monument was properly established by me on Aug. 23, 1983, and witnessed by Jim DeMastus and Tom Fisk.

**REGISTERED PROFESSIONAL LAND SURVEYOR**  
*William L. Hanley*  
**OREGON**  
 JULY 14, 1978  
 WILLIAM L. HANLEY  
 1639

Office of County Surveyor Union County of Union  
 State of Oregon, I hereby certify that the within instrument was filed in this office  
 for record on the            day of           , 19            
           by             
 (COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY SURVEYOR**  
 Date Received 9-6-83  
 Date Filed 9-12-83  
 By G. LANGUTZ, DEPUTY  
 File No. 337-83 R