


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

C-3

History of original corner establishment:

NONE: Corner established this survey.



Description of corner evidence found:

NONE

Description of monument and accessories I established to perpetuate the original location of this corner:

At position established by subdivision survey of Section 6, set a 2½ inch brass cap on a 2 inch iron pipe 31 inches long and projecting 6 inches out of the ground with surrounding earthen mound with a 6 foot steel fence post alongside with a sign 54-9 attached.

Brass cap marked thus:

T 2 S R 38 E

C $\frac{1}{4}$ S 6

1983

ORLS 1639

New bearing trees:

A fir 10 ins diam bears N 73° E, 20.2 feet dist marked C 1/4 S 6 BT

A spruce 12 ins diam bears S 38° W, 40.4 feet dist marked C 1/4 S 6 BT

Each bearing tree has a sign 54-3 attached below a 6 inch band of red paint and has a brass washer marked PLS 1639 nailed flush with BT blaze. A sign 54-4 is attached on opposite side of tree from BT blaze.

I hereby certify that the above described corner monument was properly established by me on Oct. 6, 1983, and witnessed by Jim DeMastus.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William L. Hanley

OREGON
JULY 14, 1978
WILLIAM L. HANLEY
1639

Office of.....County Surveyor..... County of.....Union.....
State of.....Oregon..... I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19.....

(COUNTY OFFICIAL)

(DEPUTY)

**UNION COUNTY
SURVEYOR**

Date Received 9-27-83 10-13-83
Date Filed 10-28-83
By G. LANGLITZ, DEPUTY
File No. 381-83 R