

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

C-5


History of original corner establishment:

Corner established by Herman D. Gradon under GLO contract no. 452 dated June 16, 1882.

Surveyor General records state:

Set a basalt stone 14 x 10 x 6 ins 9 ins in the ground for 1/4 sec cor marked 1/4 on W face from which:

A pine 6 ins diam bears N 40° E, 58 lks dist marked 1/4 S BT.
A pine 4 ins diam bears N 50° W, 22 lks dist marked 1/4 S BT.




Description of corner evidence found:

NONE: Corner reestablished at single proportionate distance between the found Northeast and Southeast corners of Section 6.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set a 2 1/2 inch aluminum cap on a 2 inch aluminum pipe 30 inches long 28 inches in the ground with 2 inches projecting out of the ground with a surrounding rock mound and a 6 foot steel fence post alongside with a sign 54-4 attached.

Aluminum cap marked thus:



New bearing trees:

A fir 12 ins diam bears N 46° W, 20.3 feet dist marked 1/4 S 6 BT.
A fir 14 ins diam bears N 45° E, 30.3 feet dist marked 1/4 S 5 BT.

Each new bearing tree has a sign 54-3 nailed below a 6 inch band of red paint and a brass washer marked PLS 1639 nailed flush with BT blaze and a sign 54-4 nailed on opposite side of tree from BT blaze.

I hereby certify that the above described corner was properly monumented by me on Aug. 25, 1983, and witnessed by Tom Fisk and Jim DeMastus.

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

William L. Hanley

OREGON
JULY 14, 1978
WILLIAM L. HANLEY
1639

Office of.....County Surveyor..... County of..... Union.....
State of..... Oregon....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19.....

..... by
(COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY
SURVEYOR**
Date Received 9-6-83
Date Filed 9-12-83
By G. LANGLITZ, DEPUTY
File No. 340-83 R