

CERTIFIED RECORD OF LAND CORNER MONUMENTATION


C-9

History of original corner establishment:

Corner established by D. Thompson under GLO contract no. 103 dated Sept. 3, 1863.

Surveyor General records state:

Set post for 1/4 Sec corner from which:
A larch 8 ins diam bears N 40° W, 50 lks dist
A pine 6 ins diam bears N 80° E, 69 lks dist




Description of corner evidence found:

NONE

Description of monument and accessories established to perpetuate the original location of this corner:

At position established by proportionate measurement between the reestablished Northeast corner of Section 5 and the found Southeast corner of Section 5 set a 2½ inch aluminum cap on a 2 inch aluminum pipe 30 inches long and projecting 6 inches out of the ground with a surrounding rock mound and a 6 foot steel fence post alongside with a sign 54-4 attached.

Aluminum cap marked thus:



New bearing trees established:

A tamarack 11 ins diam bears N 20° E, 19.7 ft dist marked 1/4 S 4 BT
A pine 8 ins diam bears N 44° W, 18.6 ft dist marked 1/4 S 5 BT

Each new bearing tree has a sign 54-3 attached below a 6 inch band of red paint and has a brass washer marked PLS 1639 nailed flush with BT blaze. A sign 54-4 is attached on the opposite side of tree from BT blaze.

I hereby certify that the above described corner monument was properly established by me on Nov. 2, 1983, and witnessed by Jim DeMastus.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William L. Hanley

OREGON
JULY 14, 1978
WILLIAM L. HANLEY
1639

UNION COUNTY
SURVEYOR

Date Received 11-10-83

Date Filed 11-14-83

By G. LANGLITE, DEPUTY

File No. 400-83 R

Office of County Surveyor County of Union
State of Oregon I hereby certify that the within instrument was filed in this office
for record on the day of , 19
by (COUNTY OFFICIAL) (DEPUTY)