


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

D-3

History of original corner establishment:

NONE: Corner established this survey.




Description of corner evidence found:

NONE: Corner established this survey.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2½ inch brass cap on a 2 inch iron pipe 31 inches long projecting 5 inches out of the ground with a surrounding rock mound and a 6 foot steel fence post alongside with a sign 54-9 attached.

Brass cap marked thus:



New bearing trees established:

A spruce 9 ins diam bears N 13° E, 35.8 ft dist marked CS 1/16 S 6 BT

A fir 9 ins diam bears S 38° E, 38.2 ft dist marked CS 1/16 S 6 BT

Each new bearing tree has a sign 54-3 attached below a 6 inch band of red paint and has a brass washer marked PLS 1639 nailed flush with BT blaze. A sign 54-4 is attached on the opposite side of tree from BT blaze.

I hereby certify that the above described corner monument was properly established by me on Oct. 27, 1983, and witnessed by Jim DeMastus.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*William L. Hanley*

OREGON  
JULY 14, 1978  
WILLIAM L. HANLEY  
1639

Office of..... County Surveyor ..... County of..... Union  
Oregon

State of..... I hereby certify that the within instrument was filed in this office  
for record on the..... day of....., 19.....

(COUNTY OFFICIAL)

(DEPUTY)

UNION COUNTY  
SURVEYOR

Date Received 11-16-83

Date Filed 11-18-83

By G. LANGLITZ, DEPUTY

File No. 407-83 R