


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:
NONE: Corner established this survey.



Description of corner evidence found:
NONE

ATTENTION
THIS DOCUMENT HAS BEEN REVISED,
By G. LANGLITZ J.S.
SIGNATURE

Date 11-30-83

REFERENCES: _____

REVISED AT REQUEST OF
Wm. HANLEY LS 1639


Noted: G. Langlitz, Union County Surveyor, Deputy

Date: 11-30-83

Description of monument and accessories I established to perpetuate the original location of this corner:

At position established by survey between Sections 5 and 6, set a 2½ inch aluminum cap on a 2 inch aluminum pipe 30 inches long and projecting 6 inches out of the ground with a surrounding rock mound and a 6 foot steel fence post alongside with a sign 54-9 attached.

Aluminum cap marked thus:



New bearing trees:

A pine 13 ins diam bears S 02° W, 21.2 feet dist marked S 1/16 S 6 BT
A fir 13 ins diam bears N 52° E, 52.7 feet dist marked S 1/16 S 5 BT

Each bearing tree has a sign 54-3 attached below a 6 inch band of red paint and has a brass washer marked PLS 1639 nailed flush with BT blaze. A sign 54-4 is attached on opposite side of tree from BT blaze.

I hereby certify that the above described corner monument was properly established by me on October 6, 1983, and witnessed by Jim DeMastus.

Office of... County Surveyor County of... Union
State of... Oregon I hereby certify that the within instrument was filed in this office for record on the... day of... 19...
by _____
(COUNTY OFFICIAL)

REGISTERED PROFESSIONAL LAND SURVEYOR
William L Hanley
OREGON
JULY 14, 1978
WILLIAM L. HANLEY
1639

UNION COUNTY SURVEYOR
Date Received 10-13-83
Date Filed 10-28-83
By G. LANGLITZ, DEPUTY
File No. 380-83 R