


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

D-7

History of original corner establishment:

NONE: corner established this survey.




Description of corner evidence found:

NONE: corner established this survey.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2½ inch aluminum cap on a 2 inch aluminum pipe 30 inches long and projecting 5 inches out of the ground with a surrounding rock mound and a 6 foot steel fence post alongside with a sign 54-9 attached.

Aluminum cap marked thus:



New bearing trees established:

A pine 14 ins diam bears N 54° E, 31.6 ft dist marked CS 1/16 S 5 BT

A pine 14 ins diam bears S 75° W, 15.0 ft dist marked CS 1/16 S 5 BT

Each new bearing tree has a sign 54-3 attached below a 6 inch band of red paint and has a brass washer marked PLS 1639 nailed flush with BT blaze. A sign 54-4 is attached on the opposite side of tree from BT blaze.

I hereby certify that the above described corner monument was properly established by me on Nov. 1, 1983, and witnessed by Jim DeMastus, Brad Gordon and Tom Fisk.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*William L. Hanley*

OREGON  
JULY 14, 1978  
WILLIAM L. HANLEY  
1639

Office of..... County Surveyor..... County of..... Union  
State of..... Oregon..... I hereby certify that the within instrument was filed in this office  
for record on the..... day of..... 19.....

..... by .....  
(COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY  
SURVEYOR

---

Date Received 11-10-83

Date Filed 11-14-83

By G. LANGLITZ, DEPUTY

File No. 398-83 R