CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established by Herman D. Gradon under GLO contract no. 452 dated June 16, 1882.

Surveyor General records state:

Set post 3 ft long 3 ins square 24 ins in the ground for 4 sec cor marked 1/4 S on N face from which;

A fir 7 ins diam bears N 12° E, 5 lks dist marked 1/4 S BT. A pine 12 ins diam bears S 20° E, 17 1ks dist marked 1/4 S BT. DIAGRAM T 2 S R 38 E S 8

Description of corner evidence found:

NONE: Corner position has been obliterated by previous logging operations.

This monument reestablished at proportionate position between found adjacent sec cors. NOTE: A tree fence corner bears N 06° W, 54 feet dist from reestablished corner position

and from which the fence lines run North and West.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 21/2 inch brass cap on a 2 inch iron pipe 31 inches long with 5 inches projecting out of the ground with a surrounding rock mound and a 6 foot steel fence post alongside with a sign 54-4 attached.

Brass cap marked thus:

T 2 S R 38 E

1983

ORLS 1639

New bearing trees established:

A fir 18 ins diam bears N 88° W, 18.1 feet dist marked 1/4 S 5 BT. A fir 13 ins diam bears S 44° E, 18.5 feet dist marked 1/4 S 8 BT.

Each new bearing tree has a sign 54-3 attached below a 6 inch band of red paint and a brass washer marked PLS 1639 nailed flush with BT blaze. A sign 54-4 is attached on opposite side of tree from BT blaze.

I hereby certify that the above described corner monument was properly established by me on Oct. 19, 1983, and witnessed by Jim DeMastus.

REGISTERED PROFESSIONAL LAND SURVEYOR

Office of County Surveyor County of Union for record on the...... day of...... , 19

OREGON JULY 14, 1978 WILLIAM L. HANLEY 1639

William L. Harley

(COUNTY OFFICIAL)

Date Received 11-10-83

UNION COUNTY

DSURVEYOR

Date Filed 11~14~83

File No. <u>403-83</u>

☆ GPO- -798-276

Form R6-7100-57 (9/71)