
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established.

T 2 S R 38E F-23



DESCRIPTION OF CORNER EVIDENCE FOUND:

None

SEE SURVEY NUMBER 018-2021

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8" x 30" iron pin with 2 1/2" Aluminum cap, marked as shown below, 34" in the ground, from which:

NEW BEARING OBJECTS:

A 5/8" x 30" iron pin bears North 0° 03' East, a distance of 18.02 feet, with 1 $\frac{1}{2}$ " aluminum cap marked N RP

A 5/8" x 30" iron pin bears South 0° 03' West a distance of 20.01 feet, with 1 $\frac{1}{2}$ " aluminum cap marked S RP

Set a fence post approximately 18 feet Northerly from monument and a fence post approximately 20 feet southerly from monument.

I hereby certify that the corner was monumented on May 11, 2021.

Witness: Kyle Tucker

T2S R38E

C

N 1/16

S 12

C

2021

OPLS 83571

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010

JEFFREY S. HSU
83571

Renewal Date: June 30, 2021

I used a Leica GS18 with RTK in the establishment of the new accessories. Bearings and distances are measured to the center of the aluminum cap.

UNION COUNTY
SURVEYOR

Date Received 5/21/21

Date Filed 5/21/21

File (Ry)

011-2021R

F-23