

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner originally established by DAVID P. THOMPSON under GLO contract number 103, dated September 3, 1863

Set post for 1/4 section corner from which
A Pine 24" diameter bears N65°W 120 LKS distance.
A Pine 24" diameter bears S45°E 70 LKS distance.


Survey # 71-73 calls setting a 5/8" x 30" iron rebar

Surveys 73-78, 74-78 and 63-79 call finding monument of record.

No record of subsequent monumentation found in Union County survey records.

DESCRIPTION OF CORNER EVIDENCE FOUND:

Found 5/8" iron rebar as per survey # 71-73.




DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

In place of found iron rebar, I set a 2 1/2" x 30" aluminum pipe with 2 1/2" aluminum cap marked as shown below, 24" in the ground, with a ring of stone.

NEW BEARING OBJECTS:

- A 28" Ponderosa Pine bears N68°E, 27.37 feet marked XX BT.
- A 26" Ponderosa Pine bears S31°E, 23.73 feet marked 1/4 S9 BT.
- A 23" Ponderosa Pine bears S23°W, 6.31 feet marked X BT.
- A 10" Ponderosa Pine bears N86°W, 49.59 feet marked 1/4 S8 BT.

I hereby certify that the corner was monumented on August 12, 1996
Witness: Mark Durbin, Jeff Madsen



REGISTERED
PROFESSIONAL
LAND SURVEYOR

Gregory T. Blackman
OREGON
JULY 13, 1973
GREGORY T. BLACKMAN
991

Renewal Date: December, 31 1997

UNION COUNTY SURVEYOR

Date Received 9-16-96

Date Filed 12-18-96

Filed By R. ROBINSON, Deputy

File Number 119-1996R

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 18° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. Attached brass washers marked OPLS 991 to the BT blaze.