
### CERTIFIED RECORD OF LAND CORNER MONUMENTATION

## HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established.

#### T 2 S R 38E H-23



DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

SEE SURVEY NUMBER 018-2021

# DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8" x 30" iron pin with 2 1/2" aluminum cap, marked as shown below, 30" in the ground, from which:

#### **NEW BEARING OBJECTS:**

A 5/8" x 30" iron pin bears North 89° 53' East a distance of 11.00 feet, with 1 ½" aluminum cap marked E RP

A 5/8" x 30" iron pin bears South 89° 53' West a distance of 12.40 feet, with 1  $\frac{1}{2}$ " aluminum cap marked W RP

Set a steel fencepost 0.5 ft. East of corner.

I hereby certify that the corner was monumented on May 12, 2021.

Witness: Kyle Tucker, Emmitt Ambert

REGISTERED
PROFESSIONAL
LAND SURVEYOR

JEFFREY S. HSU 83571

Renewal Date: June 30, 2021

S 1/16 S 12

C
2021
OPLS 83571

UNION COUNTY SURVEYOR

Date Received 5/21/2

016-2021 R

I used a Leica GS18 with RTK in the establishment of the new accessories. Bearings and distances are measured to the center of the aluminum cap. Basis of bearing is as per Survey Number 018-2021.