


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established.

T 2 S R 38E H-24



DESCRIPTION OF CORNER EVIDENCE FOUND:

None

SEE SURVEY NUMBER 018-2021

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8" x 30" iron pin with 2 1/2" aluminum cap, marked as shown below, 30" in the ground, from which:

NEW BEARING OBJECTS:

A 5/8" x 30" iron pin bears North 0°02' East a distance of 30.00 feet, with 1 1/2" aluminum cap marked N RP

A 5/8" x 30" iron pin bears South 89° 53' West a distance of 30.00 feet, with 1 1/2" aluminum cap marked W RP

Set fence posts next to reference pins.

I hereby certify that the corner was monumented on May 12, 2021.

Witness: Kyle Tucker, Emmitt Ambert

REGISTERED
PROFESSIONAL
LAND SURVEYOR



OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2021

BAGETT - GRIFFITH & BLACKMAN

T2S R38E


SE 1/16 S12

2021
OPLS 83571

UNION COUNTY
SURVEYOR

Date Received 5/21/21

Date Filed 5/21/21



File Number 017-2021R

I used a Leica GS18 with RTK in the establishment of the new accessories. Bearings and distances are measured to the center of the aluminum cap. Basis of bearing is as per Survey Number 018-2021.