# CERTIFIED RECORD OF LAND CORNER MONUMENTATION

### HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner originally established by Herman D. Gradon under GLO contract Number 452, dated March 31,1882. Surveyor General record states:

Set 3 foot long 3 inch square wooden post 24 inches in the ground for 1/4 corner, from which; A 10 inch Fir marked 1/4 S BT, which bears North 30° West 7 links.

A 12 inch Fir marked 1/4 S BT, which bears South 30° West 14 links.

DESCRIPTION OF CORNER EVIDENCE FOUND: No original evidence found See Survey No. 023-2001

# T2S R38E J-03

# DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position established by Survey number 023-2001, I set a 2 1/2"x 30" aluminum monument marked as shown, 27 inches in the ground, from which;

## NEW BEARING TREES:

A 13 inch White Fir bears North 55° West, a distance of 33.60 feet, marked X BT.

A 15 inch White Fir bears South 3° East, a distance of 36.20 feet, marked 1/4 S18 BT.

A 20 inch Douglas Fir bears South  $27^\circ$  west, a distance of 55.10 feet, marked 1/4 S18 BT.

A 23 inch White Fir bears North  $63^{\circ}$  west, a distance of 43.90 feet, marked 1/4 S7 BT.

Set steel fence post approximately 1 foot North of monument. Raised a mound of stone around monument, 1 ft. base to top of cap. I hereby certify that the corner was monumented on June 1, 2001 Witnesses:

Norbert W. Volny and Gregory T. Blackman Jr.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
July 17, 1986
RICK G. ROBINSON
2219

Renewal Date December 31, 2002

ST 1/4 S18 2001
OPLS 2219

UNION COUNTY
SURVEYOR

Date Received 6/8/01

Date Filed 7/2/01

Filed By 477 1. 6/2

File Number 032-2001 R

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 18° East declination, the distances are to a 60d spike driven in the root crown of the BT. A brass washer marked OPLS 2219 is attached to the BT blaze.