
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT: No original corner established.



DESCRIPTION OF CORNER EVIDENCE FOUND:

See Survey Number 23-2001

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position established by Survey number 23-2001, I set a 5/8"x 30" iron pin with $2\frac{1}{2}$ " aluminum cap marked as shown, 30 inches in the ground, from which;

NEW BEARING TREES AND OBJECT:

A 29 inch Ponderosa Pine bears South 46° East, a distance of 32.99 feet, marked 1/16 S18 BT.

A 15 inch Douglas Fir bears South 85° West, a distance of 39.90 feet, marked 1/16 s18 BT.

Set steel fence post approximately 1 foot West of monument.

I hereby certify that the corner was monumented of June 4, 2001 Witnesses:

Norbert W. Volny and Greg T. Blackman Jr.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON

RICK G. ROBINSON

2219

Renewal Date December 31, 2002

T2S R38E

S7
E 1/16 S18

2001
OPLS 2219

UNION COUNTY
SURVEYOR

Date Received 6/8/01

Talos

Filed By Jy 7. Sa

File Number 033 - 2001 R

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 18° East declination, the distances are to a 60d spike driven in the root crown of the Bearing tree. A brass washer marked OPLS 2219 is attached to the bearing tree blaze.