
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

This corner was not established in the original survey.



No record of subsequent monumentation found in Union County survey records **DESCRIPTION OF CORNER EVIDENCE FOUND**:

NONE

See Union County Survey Number 027-1993.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

In proportionate position, determined by survey I set a $2\frac{1}{2}$ " x 30" aluminum pipe with aluminum cap marked as shown, inches in the ground, from which;

REFERENCE OBJECTS

A 5/8" X 30" rebar bears N56½°E, 79.66 feet with aluminum cap marked NE RP.


A 5/8" X 30" rebar bears S63°E, 73.06 feet with aluminum cap marked SE RP.

Raised a mound of stone around monument, 3 ft. base to top of cap.

I hereby certify that the above corner point was perpetuated as hereon described on August 5, 1993.

Witness

Jim Bennett Travis Foster



PROFESSIONAL LAND SURVEYOR

I used a steel tape and magnetic compass in the establishment of new accessories. I used 17° East magnetic declination and the distances are to the center of the aluminum cap.

DUANE I. GRIFFITH

Date Find 8/9/93

By Many 7. Black

File No.

U-25 /