


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner originally established by Timothy W. Davenport under GLO contract number 102, dated July 20, 1863. Surveyor General record states:

Set gr Sec. post, from which:
A Hemlock, 20 in. dia. bears S30°E, 12 lks. dist.
A Red Fir, 5 in. dia. bears N50°E, 5 lks. dist.

T 1S R 39 E Z-23



DESCRIPTION OF CORNER EVIDENCE FOUND:

Found no remains of the original corner.

See Survey Number 050-2013

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At proportionate position, I set a 2 1/2" x 30" aluminum pipe with 2 1/2" aluminum cap, marked as shown below, 30 inches in the ground, from which:

- A 17 inch Western Larch bears North 33° East, a distance of 14.05 feet, marked 1/4 S36 BT.
- A 12 inch Western Larch bears South 89° East, a distance of 23.75 feet, marked 1/4 S1 BT.
- A 10 inch Western Larch bears South 80° West, a distance of 24.20 feet, marked 1/4 S1 BT.
- An 11 inch Western Larch bears North 13° West, a distance of 8.98 feet, marked 1/4 S36 BT.

I hereby certify that the corner was monumented on October 7, 2013.

REGISTERED
PROFESSIONAL
LAND SURVEYOR



OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2015

BAGETT - GRIFFITH & BLACKMAN

T1S R39E

1/4 S 36

S 1

T2S

2013

OPLS 83571

**UNION COUNTY
SURVEYOR**

Date Received 10/10/13

Date Filed 10/10/13

Filed By WLG

File Number 441-2013R

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 16° East declination. The distances are to a 60d spike in the right hand side of the root crown of the new bearing trees. Bearings are to a brass washer marked OPLS 83571 in the lower BT blaze.