


# CERTIFIED RECORD OF LAND CORNER MONUMENT

## HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

The Center Quarter Corner of Section 35, Township 2 South, Range 39 East of the Willamette Meridian has not been established by the GLO, BLM or by any other Federal, State and County Agencies.

No existing information found on a private company or surveyor establishing this position.



## DESCRIPTION OF CORNER EVIDENCE FOUND:

SEARCHED FOR BUT NO MONUMENT FOUND.  
USED EXISTING FENCE CORNER POSITION FOR BEST EVIDENCE OF CORNER LOCATION.

## DESCRIPTION OF MONUMENT AND ACCESSORIES THAT I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

SET 30" LONG #6 REBAR WITH 3-1/4" DIAMETER ALUMINUM CAP AT FENCE CORNER FLUSH WITH GROUND.

## ACCESSORIES (BEARING OBJECTS):

- Set 60d Nail 3' above ground in east face of an existing wood fence post, that bears N00°E from set monument, 6.8 feet.
- Set 60d Nail 3' above ground in south face of an existing wood fence post, that bears N90°W from set monument, 6.7 feet.
- Set 7' long steel "U" Channel Post with white Sign attached, 1.0' east of set monument.
- Set 7' long steel "U" Channel Post with white Sign attached, 1.0' north of set monument.

I hereby certify that the corner was set on July 16th, 2019.  
Witnessed by: Kevin Kenna & Seth Gould


REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

OREGON  
NOVEMBER 7, 2011  
VERNEN KALANI LEE  
85504

EXPIRES: 12/31/2020

UNION COUNTY  
SURVEYOR

DATE RECEIVED: 9/20/19  
DATE FILED: 9/24/19  
FILED BY: Neal B. Minn  
FILE NUMBER: 059-2019R



FIELD CREW USED A COMPASS OR GPS WITH STEEL TAPE FOR ESTABLISHMENT OF THE NEW ACCESSORIES. ALL DISTANCES STATED ARE HORIZONTAL DISTANCES FROM CENTER OF SET ALUMINUM CAP TO THE STATED ACCESSORY.