


**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:  
Corner not previously established.

T 2S R 40 E B-03



DESCRIPTION OF CORNER EVIDENCE FOUND:  
None.

See Survey Number 050-2013

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8" x 30" iron pin with 2 1/2" aluminum cap, marked as shown below, 30 inches in the ground, from which:

A 7 inch Lodgepole Pine bears South 44° East, a distance of 21.40 feet, marked CN1/16 S6 BT.  
An 11 inch Ponderosa Pine bears South 40° West, a distance of 29.05 feet, marked CN1/16 S6 BT.

I set a steel fencepost approximately 1 foot North of the corner monument.


I hereby certify that the corner was monumented on October 9, 2013.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR



OREGON  
June 2, 2010  
JEFFREY S. HSU  
83571

Renewal Date: June 30, 2015



**UNION COUNTY  
SURVEYOR**

Date Received 10/10/13

Date Filed 10/10/13

Filed By MSH

File Number 443-2013R

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 16° East declination. The distances are to a 60d spike in the right hand side of the root crown of the new bearing trees. Bearings are to a brass washer marked OPLS 83571 in the lower BT blaze.