CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner originally established by Henry Meldrum, under GLO Contract No. 450, dated June 11, 1882. Surveyor General record states:


Set post 3 ft. long, 3 in. square, 24 ins. in ground for 1/4 Sec Cor, from which:

A Tamarack 4 in. diam. bears N9E, 15 lks. dist., marked 1/4 S BT.

A Tamarack 4 in. diam. bears S20W, 19 lks. dist.,

marked 1/4 S BT.

In Survey 113, dated September 1959, James Voelz sets a 7 ft. long 2" pipe from original corner evidence.



DESCRIPTION OF CORNER EVIDENCE FOUND:

Found a 2" iron pipe 5 ft. above ground, from which:

A 9 inch snag bears North 9° East, a distance of 9.2 feet, with scribe marks visible on an opened blaze.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

From the 2" iron pipe position, I take new bearing trees:

A 5 inch Douglas Fir bears North 46° East, a distance of 27.30 feet, marked 1/4 S6 BT.

A 14 inch White Fir bears South 34° East, a distance of 11.45 feet, marked $1/4\ S7$ BT.

A 25 inch Douglas Fir bears South 55° West, a distance of 23.20 feet, marked 1/4 S7 BT.

A 27 inch Douglas Fir bears North 53° West, a distance of 34.35 feet, marked 1/4 S6 BT.

I hereby certify that the corner was perpetuated September 30, 2013.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010

JEFFREY S. HSU
83571

Renewal Date: June 30, 2015

UNION COUNTY
SURVEYOR

Date Received 10/10/13

Date Filed 10/10/13

Filed By 434-2013K

I used a compass and steel tape in the establishment of the new accessories. I used 16° East declination. Distances to the new bearing trees are to a 50d spike in the right hand side of the tree. Distance to the new NW bearing tree is to a spike in the left side of the root crown. Bearings to the original bearing trees are to the center of the tree. Distances are to the face of the scribe.